

WELD PURGE MONITOR[®]

PurgEye[®] 500 Desk

with PurgeNet[™]

- **PurgeNet[™]** connector for smart accessories.
 - Smart accessories include:
 - Drive system for automatic welders and orbital welders.
 - Traffic light accessory for visual warning.
 - Dew point measuring monitor.
 - Temperature measuring accessory.
- PurgeLog[™] data logging software* included.
- Designed to monitor with or without the pump running continuously.
- Provided with a UK power lead with a fused plug and a series of adaptors to connect to the Mains electricity 110V - 240V single phase 50 - 60Hz.
- Reads PPM or Percentage.
- Specially designed, extra long life sensor with faster response.
- OLED screen with stunningly clear, bright figures and text.
- Power consumption 18W.
- Reading from 1000ppm - 1ppm.
- Excellent HF protection. Totally unaffected by welding arcs.
- Audible alarm features to indicate low and high levels of oxygen.
- Pump flow rate 3.5 - 4 l/m.
- Suitable for use with Welding Chambers and Enclosures as well as Orbital Welders and other Automatic Welding Systems.



* PurgeLog[™] Data Logging Software requires a PC running a minimum of Microsoft[®] Windows 95/98/XP or NT4.